

	<u>Program Name</u>	<u>Date(D)</u>	<u>Topic</u>
➔	10e40	201106	EMC
➔	10e37	201104	Working voltage
➔	10e38	201102	Temperature rise Switch mode power supplies
➔	09e35	201009	Cables - Conductor Resistance for IEC 60227
➔	09e37	201006	Working voltage
➔	09e31	201005	Tracking Test to IEC60112:2003
➔	10e39A	201003	Chemically Regulated Substances
➔	09e38	201002	Temperature rise Switch mode power supplies
➔	05e21	200911	Laser
➔	09e36	200907	Touch Current
➔	09e33	200906	Temperature Rise - Switches
➔	08e32	200904	Temperature Rise - Transformers
➔	05e22	200903	Photovoltaics
➔	09e34	200902	Ball Pressure Test
➔	08e29	200901	Glow Wire and Needle Flame
➔	09e34CSP	200809	Ball Pressure Test
➔	08e29CSP	200809	Glow Wire and Needle Flame
➔	08e31	200808	Tracking Test to IEC60112:2003
➔	07e35	200807	Cables - Conductor Resistance for IEC 60227
➔	05i27	200805	Plug Discharge
➔	07e30-2	200802	Creepage and Clearance
➔	05e27-B-17	200801	Plug Discharge
➔	05e27-B-15	200801	Plug Discharge
➔	05e27-B-14	200801	Plug Discharge
➔	05e27-B-13	200801	Plug Discharge
➔	05e27-A-24	200801	Plug Discharge
➔	05e27-A-23	200801	Plug Discharge
➔	05e27-A-22	200801	Plug Discharge
➔	05e27-A-21	200801	Plug Discharge
➔	05e27-A-20	200801	Plug Discharge
➔	05e27-A-19	200801	Plug Discharge
➔	05e27-B-12	200711	Plug Discharge
➔	05e27-B-11	200711	Plug Discharge
➔	05e27-A-18	200711	Plug Discharge

→	05e27-A-17	200711	Plug Discharge
→	05e27-A-16	200711	Plug Discharge
→	05e27-A-15	200711	Plug Discharge
→	07i02	200709	Power Input Test UL 1026 cl 31
→	07e30	200708	Creepage and Clearance
→	05e27-A-14	200708	Plug Discharge
→	05e27-B-09	200707	Plug Discharge
→	05e27-B-04	200707	Plug Discharge
→	05e27-B-03	200707	Plug Discharge
→	05e27-B-02	200707	Plug Discharge
→	05e27-B-01	200707	Plug Discharge
→	05e27-A-12	200707	Plug Discharge
→	07i01	200704	Touch Current
→	05e27-B-10	200704	Plug Discharge
→	05e27-B-08	200704	Plug Discharge
→	05e27-B-07	200704	Plug Discharge
→	05e27-B-06	200704	Plug Discharge
→	05e27-B-05	200704	Plug Discharge
→	05e27-A-13	200704	Plug Discharge
→	05e27-A-11	200704	Plug Discharge
→	05e27-A-10	200704	Plug Discharge
→	05e27-A-09	200704	Plug Discharge
→	05e27-A-08	200704	Plug Discharge
→	05e27-A-07	200704	Plug Discharge
→	05e27-A-06	200704	Plug Discharge
→	05e27-A-05	200704	Plug Discharge
→	05e27-A-04	200704	Plug Discharge
→	05e27-A-03	200704	Plug Discharge
→	05e27-A-02	200704	Plug Discharge
→	05e27-A-01	200704	Plug Discharge
→	07m01	200703	Glow Wire and Needle Flame
→	07m02	200702	Ball Pressure Test
→	05e27-B-16	200702	Plug Discharge
→	05e28_2	200610	Electric Strength Test
→	05e28_1	200607	Electric Strength Test

→	05e28pilot	200512	Electric Strength Test
→	05e26	200512	Ball Pressure Test
→	05e25	200511	Temperature Rise - Switches
→	05e24	200510	Temperature Rise - Transformers
→	05e23	200509	Glow Wire and Needle Flame
→	04e20	200505	Tracking Test to IEC60112:1993
→	04e19	200412	Ball Pressure Test
→	04e18	200411	Temperature Rise - Transformers
→	04e17	200410	Glow Wire and Needle Flame
→	03e14	200406	Creepage and Clearance to 60335
→	04e16	200404	Tracking Test to IEC60112:2003
→	03e11	200403	Creepage and Clearance
→	04e15	200402	Ball Pressure Test
→	03e9	200401	Temperature Measurement
→	01e4	200401	Glow Wire and Needle Flame
→	01e4	200312	Glow Wire and Needle Flame
→	03e11	200311	Creepage and Clearance
→	03e9	200310	Temperature Measurement
→	03e8	200309	Ball Pressure Test
→	03e8	200306	Ball Pressure Test
→	01e5	200304	Tracking Test to IEC60112:1993
→	01e4	200304	Glow Wire and Needle Flame
→	01e4	200211	Glow Wire and Needle Flame
→	01e6	200202	Creepage and Clearance
→	01e7	200105	Temperature Measurement
→	99e3	200004	Electric Strength Test
→	99e2	200003	Ball Pressure Test
→	99e1	199911	Temperature Rise - Switches

Filter Programs > :

Click any Underlined column heading to sort by that column

Add Program

Close <End>